

Radiation Safety Emergency Contacts

Emergency Contact Steps (if one step doesn't work, move on to the next)

First – Contact Lab Manager (Area of Responsibility)

Second – Contact Radiation Safety Officer (*Marron*), ARSOs (*Jaunich* or *Chateaufneuf*)

Third – Contact Assistant Radiation Safety Officer / RSC Chair (*Getto*)

Radiation Safety Officers and RSC Chair

Name	Location	Ext.	Email	
Daniel Marron (RSO)	RI-01C	3 – 5137	dmarron@usna.edu	
LT Laurel Jaunich (ARSO)	RI-351	3 - 6538	jaunich@usna.edu	After hours: Contact NADO at (443) 569-2180 to reach RSO/ARSO's
Ginger Chateaufneuf (ARSO)	MI-016A	3 – 5224	chateaug@usna.edu	
Elizabeth Getto (RSC)	RI-355	3 – 6506	getto@usna.edu	

Rickover Hall

Name	Location	Ext.	Email	
Kelly Delikat	RI-71, RI-73, RI-75A	3 – 5188	delikat@usna.edu	Reactor Lab, Neutron Generator
Brian Earp	RI-237A	3 – 6460	earp@usna.edu	Scanning Electron Microscope
Joseph Latta	RI-71, RI-73, RI-75A	3 – 5129	jlatta@usna.edu	Lab Manager (Nucleonics Lab)

Chauvenet Hall

Name	Location	Ext.	Email	
Joel Helton	CH-044	3 – 6674	helton@usna.edu	PANalytical X-Ray Diffractometer
Daryl Hartley	CH-029, CH-028	3 – 6671	hartley@usna.edu	Phys RAM Safe, Particle Accelerator
Richard Witt	CH-046	3 – 6675	witt@usna.edu	Electron Microscope Lab, PHYWE XRD

Michelson Hall

Name	Location	Ext.	Email	
Matt Buck	MI-036	3 – 5217	mbuck@usna.edu	Bruker M4 Tornado XRF
Ginger Chateaufneuf	MI-032	3 – 5224	chateaug@usna.edu	Chemistry RAM
Megan Mohadjer Beromi	MI-131	3 – 6613	mohadjer@usna.edu	Rigaku XtaLab Synergy X-ray Diffractometer

Hopper Hall

Name	Location	Ext.	Email	
Vince Morales	CERF	3 – 0958	morales@usna.edu	Source Storage

Additional Resources

Website:	www.usna.edu/radiationsafety
RSP email:	rsp-all-group@usna.edu
(A)RSO email:	rsp-arsos-group@usna.edu